

# IPM<sup>®</sup> Repair Kit

| <b>601004</b> | <b>Fluid section repair kit</b> |                   |     |
|---------------|---------------------------------|-------------------|-----|
|               | Part #                          | Description       | Qty |
|               | 500153                          | Femal gland       | 1   |
|               | 500154                          | Male gland        | 1   |
|               | 500180                          | "V" block packing | 3   |
|               | 500181                          | Piston cup        | 1   |